Translated NBI Fields
5/27/2014
by GFC

NBI Item No	BPO Item No	LP Item No	Field Name	Notes
58	663	WB76-63	Deck Condition	NBI uses N = not applicable, 9 = extremely good condition
59	671	WB76-71	Superstructure Conditon	WSBIS uses 9 = not applicable, and highest condition = 8
60	676	WB76-76	Substructure Conditon	Applies to NBI Items 58-62
61	677	WB76-77	Channel Condition	
62	678	WB76-78	Culvert Condition	
21	019	n/a	Owner	Selected codes added and removed to better reflect Washington State.
22	286	WS72-86	Custodian	Applies to NBI Items 21 and 22
3	021	n/a	County	(WSBIS Code x 2) - 1 = NBI code
2	274	WB72-74	Region	WSBIS codes NW, NC, OL, SW, SC, EA translated to 01 through 06 respectively in NBI.
33	291	WB72-91	Median	WSBIS added several codes to cover median cases not listed in NBI.
35	3102	WB73-102	Flared Flag	WSBIS codes Y or N, NBI codes 0 or 1
110	489	WB74-89	National Truck Network	WSBIS codes Y or N, NBI codes 0 or 1
102	490	WB74-90	Lane Use Direction	WSBIS expanded NBI definition to cover reversible lanes
107	546	WB75-46	Deck Type	WSBIS expanded NBI definition to cover more deck types

Fields treated differently by BPO and LP applications

NBI Item No	BPO Item No	LP Item No	Field Name	Notes
5A	432	WB74-32	Record Type (on-under code)	BPO usezs Z code to indicate "neither on nor under"; LP uses 0 code for same purpose. NBI has no code for this.
13A	467	WB74-67	LRS Route	BPO uses a 12 digit code, with last 2 characters truncated for NBI submittal. LP uses 11 characters with one trunc.
11	W07 (temp)	WB74-40	LRS Milepoint	BPO created new field LRS_traffic_flow, retained traffic_flow for non-NBI use. LP uses traffic_flow for LRS mp.
37	292	WB72-92	Historical Significance	BPO and LP codes for both NRHP and HAER (not in the same way), whereas NBI codes for NRHP only.
28B	354	WB73-54	Lanes Under	BPO migrated this data from tblBridges to tblCrossing. LP retains this data in tblBridges.
various	?	?	Inspection Types	BPO has eliminated and modified inspection types for Damage and UW report types.
various	?	?	Report Types	LP has created INDH and FETR report types
63	551	WB75-51	Operating Rating Method	BPO uses current NBI codes, but not all of them. LP uses old codes that are translated, again not all of them.
65	554	WB75-54	Inventory Rating Method	same as Item 63

Proposed Improvement Fields - BPO created new table but no translation

NBI Item No	BPO Item No	LP Item No	Field Name	Notes
75A	844	WB78-44	Type of Work Proposed	BPO created new tlbProposedImprovements, LP keeps this data in tblBridges for all proposed improvement
75B	846	WB78-46	Work Done By	fields
76	847	WB78-47	Proposed Improvement Length	
94	869	WB78-67	Structure Cost	
95	873	WB78-73	Roadway Cost	
96	861	WB78-61	Total Project Cost	
97	879	WB78-79	Estimate Year	